

Croxden PC Highways Reporting Log – 2020-2023

Reported to Staffordshire County Council via Highways Report IT tool.

www.staffordshire.gov.uk/reportit

Reported issue – location and requested action	Date reported	Highways reference number	Follow up date	Comments
<p>Grass encroaching footpath – Beamhurst.</p> <p>From Beamhurst View all the way to Newlands Barn</p> <p>ST14 5EA</p>	15.04.2021	4238187	22.04.2021	<p>Residents asked for it to be cleared in the bulb planting letter replies</p> <p>This is an update to your enquiry dated 15/04/2021 in relation to Uttoxeter Road.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Thank you for your enquiry.</p> <p>All roads connected to Staffordshire’s highway network are routinely inspected to identify safety defects. Any issues that are identified are raised for repair and categorised according to urgency.</p> <p>Should you have any concerns regarding a specific defect, please contact us with detailed information and we will assist you where possible</p>
		4256117	24.09.21	<p>At meeting with Parish council to discuss bulb planting residents at Beamhurst reported overgrown vegetation encroaching on the footpath running alongside the A522 through Beamhurst.</p>
			01.10.21	<p>Reply stating, “ A Highways Inspector has now assessed the site you reported and arranged a non-urgent work instruction ... This means that non-urgent repairs are likely to be grouped with other works and repair timescales will reflect this”.</p>
<p>Speed Limit Signs – faded by Meachen and Bevan A522 Beamhurst ST14 5DZ</p>	22.04.2021	4238877	17.05.2021	<p>Reported to Clerk by resident</p> <p>This is an update to your enquiry dated 22/04/2021 in relation to UTTOXETER ROAD.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report:</p> <p>Thank you for your enquiry work has already been raised for multiple signs to be replaced in this location and will be carried out as soon as scheduling and resources allow</p>
		4256116	24.09.21	<p>Reported by several Beamhurst residents during meeting with Parish Councillors to discuss bulb</p>

				planting in Beamhurst. Report to Highways pointed out that faded sign might be contributing to the ongoing speeding issue along the A522.
Speed Limit Signs – slipped down Roundabout By JCB Waterloo Park Beamhurst ST14 5PA	22.04.2021	4238878	17.05.2021	Reported to Clerk by resident This is an update to your enquiry dated 22/04/2021 in relation to Uttoxeter Road. A highways inspector has now assessed the site you reported and arranged a non-urgent works instruction.
Speeding Traffic along A522 –from Watery Lane to Madeley Farm, ST14 5EA postcode used Reported via traffic management, then traffic calming buttons	03.06.2021	4243806	21.07.21	Resident sent email to Council Report wording was Traffic calming measures have been requested by residents to the Parish Council to be installed along the A522 from Madeley Farm to Watery Lane, Beamhurst – currently cars and motor bikes exceed the speed limit along this stretch of the road, and there are a number of driveways (18) that lead onto the road and residents are concerned. Speeding Concerns article put on website and FB page. All details given to the resident that requested traffic calming measures. Clerk advised the resident to ask all local residents to report their concerns to both SCC and Staffordshire Safer Roads Partnership. Report from Highways: This is an update to your enquiry dated 03.06.2021 in relation to Uttoxeter Road. A highways officer has now considered your enquiry and added the following notes to your report: Thank you for your enquiry and apologies for the delay in responding. Uttoxeter Road in Beamhurst is currently under investigation and Cllr Atkins has agreed to fund a feasibility study to determine the issues and any suitable traffic calming solutions.
Faded road markings on A522 running through Beamhurst ST14 5EA & ST14 5DZ	13.09.21	4256112	24.09.21 01.10.21	During meeting with Parish Council to discuss bulb planting in Beamhurst, several residents raised concerns regarding faded road markings. Reply stating, “A Highways Officer has now considered your enquiry and added the following notes to your report. We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at his time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections”.
ST14 5EA Loose manhole cover by School	13.09.21	4256111	24.09.21	During meeting with Parish Council to discuss bulb planting in Beamhurst, residents raised concerns regarding loose manhole cover

House Farm, Beamhurst A522			01.10.21	Reply stating, "A Highways Inspector has now assessed the site you reported and arranged a non-urgent work instruction ... This means that non-urgent repairs are likely to be grouped with other works and repair timescales will reflect this"
ST14 5EA Noise pollution – A50 – affecting Beamhurst residents	04.09.21	Highways England Reference 22065001 - Noise HECCC:07850	27.09.21	Residents at Beamhurst raised concerns with Parish Council (via email and during meeting with Parish Council to discuss bulb planting) regarding noise from A50 road. Report sent to Highways England stating, "Several residents living in the village of Beamhurst, which is parallel to the A50 road between Uttoxeter and Stoke-on-Trent, have complained to Croxden Parish Council about longstanding traffic noise on the A50 due to poor surfacing. Residents want this section of the A50 to be resurfaced in order to reduce noise pollution in the village".
			06.10.21	<p>The following reply received from Janet Baley, Service Delivery Manager, A50 DBFO at National Highways::</p> <p>Thank you for contacting National Highways regarding at properties in the village of Beamhurst. I am National Highways Service Delivery Manager for the A50, I'm responding to you as this issue falls within my area of responsibility.</p> <p>The way in which we manage traffic noise issues on the Strategic Road Network is driven by the requirements of the Environmental Noise (England) Regulations 2006 via the Department for Environment, Food and Rural Affairs (Defra). These regulations require strategic noise maps and action plans to be undertaken on a five-year cycle. The current strategic noise maps were published in July 2019.</p> <p>As part of the Environmental Noise Directive 2002/49/EC, Defra published 'Round 1' strategic noise maps for England's roads in 2008 and the Noise Action Plans in 2010. The action plans set out guidelines for managing noise rather than proposing specific solutions and the strategic noise maps established the locations of 'Important Areas' (sometimes referred to as noise 'hotspots') that are impacted from major sources of noise and therefore must be investigated. The Strategic Road Network is one of these major sources of noise and the 'Important Areas' established by Defra represent areas that contain the top 1% of the population exposed to high noise levels from major roads. Defra has now completed the latest version (Round 3) of the Noise Action Plans and these were published on 2nd July 2019.</p> <p>For more information on how the strategic noise mapping were created, please see following link: https://www.gov.uk/government/publications/strategic-noise-mapping-2019</p>

				<p>I have reviewed our database for Beamhurst, it confirms properties at this location have not been identified as 'Important Areas' (a noise 'hotspot') by Defra, which mean that they are not being exposed to the highest noise levels generated by the Strategic Road Network.</p> <p>However, we acknowledge that noise from our Strategic Road Network can still affect the quality of life for those living nearby, yet still outside of an 'Important Area'. Whilst we are unlikely to provide specific noise mitigation measures, such as noise barriers, at these locations in the near future, we are working to minimise noise emissions from the Strategic Road Network as a whole, through the use of low noise surfacing as our standard surface, which will gradually replace older, noisier surfaces, and looking at ways that we can encourage road users to fit quieter tyres to their vehicles.</p>
<p>ST14 5JD Truckle House, Croxden</p> <p>On the road between the bridge spanning Croxden brook and the bend where Truckle House and the newly converted barn are situated.</p>	07.12.2021	4263354	13.12.2021	<p>Water is collecting and not running down the grid. WH Durose advised it needs to be jetted out.</p> <p>Report made to Highways, stating that several times in the course of the year flooding has occurred (on a few occasions culminating in a large pool developing on the road) making it impossible for walkers to pass, and presenting a risk to cyclists and motorists.</p> <p>Reply received stating, "A Highways inspector has now assessed the site you reported and identified drainage maintenance works that will be addressed during the next planned cleansing operation".</p>
<p>ST10 4HF Stonehill, Greatgate FORD</p>	12.01.2022	4266393 4268673 4275711	02.02.22 09.02.22 21.03.22 11.04.22	<p>Significant road deterioration has occurred on the road beside the brook running alongside Sandy Lane, resulting in a number of potholes forming next to each other and amalgamating.</p> <p>Further report made to Highways re deterioration to pothole.</p> <p>Report from Highways received stating, NON URGENT WORK "A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. This means that non-urgent repairs are likely to be grouped with other works and repair timescales will reflect this".</p> <p>Further report made to Highways re continued deterioration to pothole.</p> <p>A report from Highways UNABLE TO ACTION "Thank you for your enquiry, when reporting a highway defect such as pothole or blocked gully, you are only able to report one defect at a time so we can allocate a reference number to each defect on site and enable you to check the progress of each report. All roads on Staffordshire's highway network receive routine highways safety inspections dependent on their road classification. If you are concerned about a</p>

		4279647	26.04.22	length of road (or more than one defect), this will be addressed on the next routine highway safety inspection. We are unable to provide a reference number for you to track progress of a report about a length of road". Further report made to Highways: "See also references 4266393, 4268673, 4275711 The pothole has increased significantly in depth, width and length since last report. Vehicles have to now move into the centre of the road to avoid the pothole. Current size 11 cms deep, 82 cms length, 67 cms width"
		4287058	04.07.22	A local resident reported to Parish Council that the pothole that had been repaired has developed a deep hole again.
		4279647	03.2023	Report from Highways, "An operational team have visited the location you provided in your report and can confirm that work has already taken are planned at this time".
		4268673	03.2023	Report from Highways, "An operational team have visited the location you provided in your report and can confirm that work has already taken are planned at this time".
ST10 4HF Stonehill, Greatgate by the Ford	02.02.2022	4268703	09.02.22	Report to Highways of pothole on the stretch of road running parallel to the brook just past the ford at Greatgate. Report from Highways stating, NO FURTHER HIGHWAYS ACTION "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
ST10 4HF, Stonehill, Greatgate by the Ford	02.02.2022	4268699	09.02.22	Report to Highways regarding a series of potholes that have emerged on the road running parallel to the brook as it flows past the ford at Greatgate. Photographs sent. Report from Highways stating, NO FURTHER HIGHWAYS ACTION "Thank you for your enquiry, when reporting a highway defect such as pothole or blocked gully, you are only able to report one defect at a time so we can allocate a reference number to each defect on site and enable you to check the progress of each report. All roads on Staffordshire's highway network receive routine highways safety inspections dependent on their road classification. If you are concerned about a length of road (or more than one defect), this will be addressed on the next routine highway safety inspection. We are unable to provide a reference

				number for you to track progress of a report about a length of road.
ST10 4HF Stonehill Greatgate by the Ford.	02.02.22	4268705	09.02.22	<p>Report to Highways regarding pothole that has emerged just past the ford at Greatgate. Photograph sent.</p> <p>Report from Highways stating, NO FURTHER HIGHWAYS ACTION - "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".</p>
ST10 4BN Greatgate Lane, Alton Spond Farm	21.03.22	4275716	11.04.22	<p>Report to Highways regarding pothole in the road by Spond Farm. Photograph sent.</p> <p>Report from Highways NON –URGENT WORK "A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.</p>
		4319569	03.04.2023	<p>Report to Highways, "A deep pothole is sited on narrow lane necessitating vehicles to swerve to avoid".</p>
ST10 4BN Greatgate Lane, Alton Spond Farm	21.03.22	4275718	11.04.22	<p>Report to Highways regarding pothole in the road by Spond Farm. Photograph sent.</p> <p>Report from Highways NON –URGENT WORK "A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available</p>
ST10 4HF Sandy Lane Greatgate Sign	21.03.22	4275865	11.04	<p>Report to Highways regarding damage to the sign for Greatgate on the approach to Greatgate via the ford on Sandy Lane.</p> <p>Report from Highways PLANNED WORK "A Highways Officer has now assessed the site and has deemed it not requiring safety intervention at this time, however a work instruction has been raised for forward planning. The report will remain on our records and the location will be routinely inspected for any changes in the level of risk".</p>
			06.22	<p>A further report make to Highways regarding the damage to the Greatgate sign.</p>
			20.12.22	

				Report from Highways: Current status ONGOING. "We have not yet been able to co-ordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network. We write to assure you that we have not forgotten about the issue and will endeavour to schedule the necessary works as soon as is practicably possible".
Alton Lane Greatgate	21.03.22	4275797	11.04.22	Report to Highways regarding one pothole amongst a series of potholes between the hamlet of Greatgate and Alton. Photographs sent. Highways Report UNABLE TO ACTION "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
Alton Lane Greatgate	21.03.22	4275806	11.04.22	Report to Highways regarding one pothole amongst a series of potholes between the hamlet of Greatgate and Alton. Photographs sent. Highways Report UNABLE TO ACTION "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
Alton Lane Greatgate	21.03.22	4275800	11.04.22	Report to Highways regarding one pothole amongst a series of potholes between the hamlet of Greatgate and Alton. Photographs sent. Highways Report UNABLE TO ACTION "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
Alton Lane Greatgate	21.03.22	4275804	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent. Highways Report UNABLE TO ACTION "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".

			17.05.23	Report from Highways: "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
Alton Lane Greatgate	21.03.22	4275867	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent. Highways Report UNABLE TO ACTION "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
			17.05.23	Report from Highways: "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
Alton Lane Greatgate	21.03.22	4275870	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent. Highways Report UNABLE TO ACTION "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although threa may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".
			17.05.23	Report from Highways: "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections".

<p>ST10 4HF Warilow Brook Alton Lane</p>	<p>21.03.22</p>	<p>4275873</p> <p>4319573</p>	<p>11.04.22</p> <p>03.04.23</p> <p>17.05.23</p>	<p>Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent.</p> <p>Report from Highways NON-URGENT WORK A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.</p> <p>Report to Highways, "A deterioration in this pothole, which has become deeper; is concealed when filled with water resulting in oncoming vehicles driving into it".</p> <p>Notification from SSC Highways: JOB RAISED</p>
<p>Alton Lane Greatgate</p>	<p>21.03.22</p>	<p>4275874</p>	<p>17.05.23</p> <p>11.04.22</p> <p>17.05.23</p>	<p>Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent.</p> <p>Notification from SSC Highways: JOB RAISED Report from Highways NON-URGENT WORK A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.</p> <p>Notification from Highways: JOB RAISED</p>
<p>Alton Lane Greatgate</p>	<p>21.03.22</p>	<p>4275876</p>	<p>11.04.22</p> <p>17.05.23</p>	<p>Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent</p> <p>Report from Highways UNABLE TO ACTION We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. It might be that the problem has now been resolved, however if you believe there is still an issue that requires attention may we kindly ask that you contact us again with your reference number and a detailed location, so we can verify the details.</p> <p>Report from Highways: "We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time".</p>

Alton Lane Greatgate	21.03.22	4275875	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent.
			17.05.23	Report from Highways UNABLE TO ACTION We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time. It might be that the problem has now been resolved, however if you believe there is still an issue that requires attention may we kindly ask that you contact us again with your reference number and a detailed location, so we can verify the details.
			17.05.23	Report from Highways: "We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time".
ST10 4HF Wood Farm Alton Lane Greatgate	21.03.22	4275788	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent.
			17.05.23	Report from Highways NON-URGENT WORK A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.
				Notification from Highways: JOB RAISED
ST10 4HF Wood Farm Alton Lane Greatgate	21.03.22	4275784	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent.
			17.05.23	Report from Highways NON-URGENT WORK A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.
				Notification from Highways: JOB RAISED
ST10 4HF Wood Farm Alton Lane Greatgate	21.03.22	4275788	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent.
				Report from Highways NON-URGENT WORK

				A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available
ST10 4HF Wood Farm Alton Lane Greatgate	21.03.22	4275784	11.04.22	Report to Highways regarding one pothole amongst a series of potholes along Alton Lane between the hamlet of Greatgate and Alton. Photographs sent. Report from Highways NON-URGENT WORK A Highways Officer has now assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available
ST10 4HF Opposite to the Bradley/Threapwood Junction on Alton Lane.	23.06.22	4285969	17.05.23	Damage to the kerb on side of Alton Lane has resulted in deep depression at side of road. Due to narrowness of the lane at this point, there is a risk of damage to vehicles seeking to avoid oncoming traffic at this point, and for small vehicles to become stuck in the depression. Report from Highways: "We have inspected the location provided with your report and were not able to identify any defects posing a safety risk that require remedial works at this time. Although the area may show aesthetic signs of deterioration the County Council is not in a position to carry out works to address this. We will continue to monitor this site during routine safety inspections Verge override not meeting intervention level."
ST14 5PA Beamhurst A522 Uttoxeter Road Roundabout by JCB	17.08.22	4296483		A cluster of potholes or surface dressing is in the centre of the road, causing drivers to swerve at the approach to the roundabout.
ST14 5PA Beamhurst A522 Uttoxeter Road Roundabout by JCB Beamhurst Factory	17.10.22	4296842		Report to Highways of large pothole by the bus stop. Photograph sent Current Status: UNABLE TO ACTION. Thank you for your enquiry. We can confirm that work has been raised for multiple defects in this area, which will be carried out as soon as scheduling and resources allow.
ST14 5PA Beamhurst A522 Uttoxeter Road Roundabout	17.10.22	4296483		Report to Highways regarding a cluster of pot holes or surface dressing is in the centre of the road, causing drivers to swerve at the approach to the roundabout. Photographs sent.

by JCB Beamhurst Factory				Report from Highways. Current Status: UNABLE TO ACTION. Thank you for your enquiry, We can confirm that work has been raised for multiple defects in this area, which will be carried out as soon as scheduling and resources allow.
ST10 4HF Sandy Lane Next to Greatgate Village Green	30.11.22	4301560		Pothole is becoming increasingly deeper and longer on the side of Sandy Lane resulting in vehicles having to swerve towards the middle of the road to avoid. This becomes dangerous when there are vehicles approaching.
ST10 4HF Greatgate hFord Sandy Lane	10.01.23 16.01.23	4305207	20.02.23	A series of potholes of varying sizes have re-emerged on road after only being filled in a few months ago, which necessitate vehicles/cyclists having to navigate around to avoid damage to vehicles/bicycles. Request from local resident: "There are a series of potholes by the ford at Greatgate where it was repaired in 2022 – but already rapidly breaking up. Also, the road surface outside Smithy Cottage (Greatgate) is starting to break hdown and will be potholes soon. Are you able to log please on behalf of the Parish Council". Local resident advised that a report had already been made by the Parish Council and it was suggested that the resident also report the matter directly to Highways in order to add weight to the initial report.
New Salt Bin Abbey View Barn Keelings Lane Croxden ST14 5JF	23.01.2023	4307817	14.03.2023	New Salt bin requested, as current one lets in water, as lid does not fit. (Holes drilled into side of bin to release water) Report from Highways: Current Status: Work Raised. "A Highways Officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose and immediate risk to public safety".
Ford Sign Sandy Lane ST10 4HE	07.03.2023	4314161	05.04.2023	A Ford sign requested on the approach to Greatgate ford from the direction of Tean/Cheadle. Report from Highways – Unable to Action – "Our Community Highways Team meet biannually with Councillors with a view to prioritising local issues for further investigation and/or action. Your concerns will be discussed with your local Councillor at the next Divisional Highway Programme (DHP) meeting. We

				receive a vast number of requests from communities for improvements to the local highway network and the DHP provides the CouGJncil with a platform to investigate some of these concerns, which may not otherwise meet the criteria for intervention”.
ST10 4HF Greatgate Ford Sandy Lane	29.03.23	4318523		Report to Highways: Mud has emerged and congregated at the side of Croxden brook where it runs immediately parallel to Sandy Lane, resulting in damage to the road surface in that section and potholes developing. The mud needs to be cleared away.
ST10 4HF Near Warilow Brook Alton Lane	03.04.2023	4319424		Report to Highways: “Local residents complain about lack of signage on Sandy Lane near Warilow brook. Due to sat nav issues, the lane is increasingly used as a short cut by Alton Towers visitors resulting in a significant increase in Alton Towers traffic on this lane. Of increasing concern is the fact that visitors are unfamiliar with driving along narrow and windy lanes, and drive at too high a speed/take bends too quickly without seeing if there is oncoming traffic. Signage is needed to alert vehicles to slow down because of sharp bends and inclines. Croxden parish council and other local councils meet regularly with Alton Towers to discuss above concerns, which are acknowledged by all”. “Warilow brook is sited in a valley with sharp inclines and bends on the road approaching from both directions. Traffic speeds up as it descends into the valley and takes bends too quickly”.
ST10 4BN Between The Spond Farm & Gallows Green Alton	03.04.2023	4319568	17.05.23	Road surface damage is becoming deeper. This is a narrow lane and the surface damage is sited on a bend. Vehicles have to move into the centre of the lane to avoid the pothole, which places vehicles directly in the path of any traffic approaching around the bend from the opposite direction, thereby placing both vehicles at risk of collision. Notification from Highways: NOT INSPECTED YET
ST10 4BN The Spond Farm Alton Lane	03.04.2023	4319570	17.05.23	Report to Highways, “Surface damage to road close to pothole (ref 4319569) mean that vehicles have to swerve into the centre of narrow lane to avoid both”. Notification from Highways: NOT INSPECTED YET
ST10 4HF Warilow Brook Alton Lane	03.04.2023	4319576		Report to Highways, “Surface damage to road is deteriorating and becoming deeper necessitating traffic to swerve to avoid. This road damage is close to a deep pothole (ref 4275873 & 4319573).

			17.05.23	Notification from Highways: NOT INSPECTED YET
ST10 4HF Between Holly Bank & Wood Farm	11.04.2023	4319595	17.05.23	Pothole in the centre of narrow lane is increasing in size and depth necessitating vehicles having to swerve to avoid. Notification from Highways: NOT INSPECTED YET
ST10 4HF Between Holly Bank & Wood Farm	11.04.2023	4319598	17.05.23	A long length of surface damage to road next to a cluster of potholes. Notification from Highways: NOT INSPECTED YET
	11.04.2023	4319599	17.05.23	Pothole on narrow lane, next to cluster of smaller potholes and long length of road surface damage, necessitating vehicles having to swerve on narrow lane to avoid. Notification from Highways: NOT INSPECTED YET
ST14 5JD Homestead Farm Hollington Road	17.04.2023	4321800	21.04.2023 at 1443 hours 21.04.2023 at 1445 hours	Water leak from metal water manhole cover, underneath Homestead Farm sign, on road side Two photos provided Also reported to South Staffs Water, Ref Number: 039FHRCU https://www.south-staffs- water.co.uk/incidents/report-a-leak Report from Highways – Urgent Received – “The event on the highway you have reported may require serious and immediate attention. It may be necessary for us to divert resources from other urgent and routine highway activities in order to assess/remedy the problem. We will review your report as soon as possible” A further report from Highways – Declassification – “The information you provided has been reviewed and currently, the defect does not warrant diverting resources on an emergency basis. Your defect will be assessed with our regular inspections and an update will be provided once complete”.

24.05.2023