

Croxden PC Highways Reporting Log – 2024

Reported to Staffordshire County Council via Highways Report IT tool.

www.staffordshire.gov.uk/reportit

Reported issue – location and requested action	Date reported	Highways reference number	Follow up date	Comments
<p>Speeding Traffic along A522 –from Watery Lane to Madeley Farm, ST14 5EA postcode used</p> <p>Reported via traffic management, then traffic calming buttons</p>	03.06.2021	4243806	<p>21.07.21</p> <p>22.04.2024</p>	<p>Resident sent email to Council</p> <p>Report wording was Traffic calming measures have been requested by residents to the Parish Council to be installed along the A522 from Madeley Farm to Watery Lane, Beamhurst – currently cars and motor bikes exceed the speed limit along this stretch of the road, and there are a number of driveways (18) that lead onto the road and residents are concerned.</p> <p>Speeding Concerns article put on website and FB page.</p> <p>All details given to the resident that requested traffic calming measures. Clerk advised the resident to ask all local residents to report their concerns to both SCC and Staffordshire Safer Roads Partnership.</p> <p>Report from Highways: This is an update to your enquiry dated 03.06.2021 in relation to Uttoxeter Road.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report: Thank you for your enquiry and apologies for the delay in responding. Uttoxeter Road in Beamhurst is currently under investigation and Cllr Atkins has agreed to fund a feasibility study to determine the issues and any suitable traffic calming solutions.</p> <p>The Parish Council are in discussions with SCC to resolve the issue.</p>
<p>ST14 5JD Truckle House, Croxdon</p> <p>Grid Blocked and water collects, covering half of the road surface</p> <p>On the road between the bridge spanning Croxdon brook and the bend</p>	<p>07.12.2021</p> <p>10.11.2023</p>	<p>4263354</p> <p>4350593</p>	<p>13.12.2021</p>	<p>Water is collecting and not running down the grid. Parish Council Lengthsman advised it needs to be jettied out.</p> <p>Report made to Highways, stating that several times in the course of the year flooding has occurred (on a few occasions culminating in a large pool developing on the road) making it impossible for walkers to pass, and presenting a risk to cyclists and motorists.</p> <p>Reply received stating, “A Highways inspector has now assessed the site you reported and identified</p>

<p>where Truckle House and the newly converted barn are situated.</p> <p>The drain cover is fused in place so needs to be removed.</p>		4351901	20.11.2023	<p>drainage maintenance works that will be addressed during the next planned cleansing operation".</p> <p>Report to Highways, " The grid line on the roadside drain is fused shut and can not be released to clear the soil and leaves from the drain. Currently there is a large amount of water collecting as the grid can not be opened to be cleared.</p> <p>A further report made to Highways, "The water continues to collect after every rainfall and covers one side of the road. Please replace the grid and clean it out so that the water can run away and not cause standing water.</p>
		4362664	15.01.2024	<p>Reported again, as nothing done and standing water is now covering half of the road.</p>
			06.02.2024	<p>A Highways Officer has attended the location that you reported and completed a risk assessment. A works order has been raised and you should have now received an email explaining the priority of the works.</p>
			07.02.2024	<p>email received:</p> <p>A highways officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety.</p>
		4392865	10.05.2024	<p>We have not yet been able to coordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network.</p> <p>We write to assure you that we have not forgotten about the issue and will endeavour to schedule the necessary works as soon as is practicably possible.</p> <p>24.05.2024 – sent email to Richard Rayson, SCC Highways</p> <p>10.06.2024 – reported again, providing photo of blocked drain cover (full of mud) and pot holes as a result of water lying on the road. Sent email to Richard, Sam Griffiths and Lisa Hall</p>
<p>Ford Sign</p> <p>Sandy Lane Greatgate</p>	07.03.2023	4314161		<p>A Ford sign requested on the approach to Greatgate ford from the direction of Tean/Cheadle.</p>

ST10 4HE			05.04.2023 22.04.2024 26.04.2024 CLOSED	<p>Report from Highways – Unable to Action – “Our Community Highways Team meet biannually with Councillors with a view to prioritising local issues for further investigation and/or action. Your concerns will be discussed with your local Councillor at the next Divisional Highway Programme (DHP) meeting. We receive a vast number of requests from communities for improvements to the local highway network and the DHP provides the Council with a platform to investigate some of these concerns, which may not otherwise meet the criteria for intervention”.</p> <p>Sent email to Cllr Atkins at SCC asking for an update.</p> <p>Update from SCC~:</p> <p>A highways officer visited the site and concluded there is sufficient signage on both approaches to the Ford, with the distance plate also in place to give advanced notice.</p>
ST14 5HY Bridge crossing Nabb Brook, Hollington Road	26.10.2023	4348300	26.10.23 22.04.2024	<p>Report to Highways, “Damage caused to bridge when lorry reversed into it. Damage caused to first three stones on left side of bridge as bridge is approached from Rocester direction.</p> <p>Report from Highways, “Your enquiry has been passed to a structural engineer to review”.</p> <p>Still on system for engineer to visit</p>
ST10 4HE Between water plant and Quarry Bank junction on Sandy Lane, Great Gate Pothole	06.11.2023	4349766	13.11.2023 22.04.2024 05.05.2024	<p>Report to Highways regarding pothole on Sandy Lane</p> <p>Report from Highways: WORK RAISED</p> <p>“A Highways Officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problem on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time as resources become available”.</p> <p>Work has been generated to resolve your request.</p> <p>We have not yet been able to coordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network.</p>

				We write to assure you that we have not forgotten about the issue and will endeavour to schedule the necessary works as soon as is practicably possible.
Greatgate – Gully blocked under tree, by Greatgate Village Green ST10 4HF	15.01.2024	4362662	22.04.2024	First noticed in November, the gully is under a tree and the tree needs removing to ensure gully is kept clear. Council obtained a quote from Lengthsman but work too big for Council to undertake. voted to report to SCC in January 2024 meeting. Your enquiry is currently allocated to a Highways officer and will be updated as soon as possible
Faded yellow rumble strips on approach to bridge on A522 Beamhurst ST14 5EA Nearest postcode Meachen and Bevan	22.04.2024	4385247		
Spond Farm, Greatgate, Alton Lane, ST10 4BN Pot holes on corner.	22.04.2024	4385249		March 2024 PC meeting it was reported that on Alton Lane, by Spond Bank Farm potholes, verge collapsed and manhole cover collapsed
Spond Farm, Greatgate, Alton Lane, ST10 4BN manhole collapsed	22.04.2024	4385252	22.04.2024	We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time.
Spond Farm, Alton Lane, Greatgate, ST10 4BN Verges and pull ins have deep holes, side of road collapsing	22.04.2024	4385256	21.06.2024	The inspector for your area has read your report and will consider these on the next planned inspection of the area. It's important to note that all roads in our region undergo regular safety checks, either monthly, quarterly, or annually, depending on their classification. We'll continue to monitor any unresolved issues carefully – raising works once the thresholds are met.
Greatgate Ford ST10 4HF Pot holes	22.04.2024	4385257		
Hollington Lane/Keelings Lane, Croxden nearest postcode ST14 5JD deep silt and gravel gather on the corner of	22.04.2024	4385278	22.04.2024	We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time.

Hollington Road and Keelings Lane				
Homestead Farm Hollington Road Croxden ST14 5JD Running Water from broken water value in roadside verge	22.04.2024	4385280		
Hollington Road Croxden Accident significant verge disturbance opposite gateway to Wootons Farm	14.05.2024			Accident on Hollington Road, Road Closed from 7pm- 9pm