

Croxden PC Highways Reporting Log – 2024

Reported to Staffordshire County Council via Highways Report IT tool.

www.staffordshire.gov.uk/reportit

Reported issue – location and requested action	Date reported	Highways reference number	Follow up date	Comments
<p>Speeding Traffic along A522 –from Watery Lane to Madeley Farm, ST14 5EA postcode used</p> <p>Reported via traffic management, then traffic calming buttons</p>	03.06.2021	4243806	<p>21.07.21</p> <p>22.04.2024</p>	<p>Resident sent email to Council</p> <p>Report wording was Traffic calming measures have been requested by residents to the Parish Council to be installed along the A522 from Madeley Farm to Watery Lane, Beamhurst – currently cars and motor bikes exceed the speed limit along this stretch of the road, and there are a number of driveways (18) that lead onto the road and residents are concerned.</p> <p>Speeding Concerns article put on website and FB page.</p> <p>All details given to the resident that requested traffic calming measures. Clerk advised the resident to ask all local residents to report their concerns to both SCC and Staffordshire Safer Roads Partnership.</p> <p>Report from Highways: This is an update to your enquiry dated 03.06.2021 in relation to Uttoxeter Road.</p> <p>A highways officer has now considered your enquiry and added the following notes to your report: Thank you for your enquiry and apologies for the delay in responding. Uttoxeter Road in Beamhurst is currently under investigation and Cllr Atkins has agreed to fund a feasibility study to determine the issues and any suitable traffic calming solutions.</p> <p>The Parish Council are in discussions with SCC to resolve the issue.</p>
<p>ST14 5HY Bridge crossing Nabb Brook, Hollington Road</p>	26.10.2023	4348300	<p>26.10.23</p> <p>22.04.2024</p>	<p>Report to Highways, “Damage caused to bridge when lorry reversed into it. Damage caused to first three stones on left side of bridge as bridge is approached from Rocester direction.</p> <p>Report from Highways, “Your enquiry has been passed to a structural engineer to review”.</p> <p>Still on system for engineer to visit</p>
<p>ST10 4HE</p>	06.11.2023	4349766		<p>Report to Highways regarding pothole on Sandy Lane</p>

<p>Between water plant and Quarry Bank junction on Sandy Lane, Great Gate Pothole</p>			<p>13.11.2023</p> <p>22.04.2024</p> <p>05.05.2024</p>	<p>Report from Highways: WORK RAISED</p> <p>"A Highways Officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problem on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time as resources become available".</p> <p>Work has been generated to resolve your request.</p> <p>We have not yet been able to coordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network. We write to assure you that we have not forgotten about the issue and will endeavour to schedule the necessary works as soon as is practicably possible.</p>
<p>Greatgate – Gully blocked under tree, by Greatgate Village Green ST10 4HF</p>	<p>15.01.2024</p>	<p>4362662</p>	<p>22.04.2024</p> <p>08.07.2024</p>	<p>First noticed in November 2023, the gully is under a tree and the tree needs removing to ensure gully is kept clear. Council obtained a quote from Lengthsman but work too big for Council to undertake. voted to report to SCC in January 2024 meeting.</p> <p>SCC responded 22.04.2024. Your enquiry is currently allocated to a Highways officer and will be updated as soon as possible.</p> <p>SCC responded 08.07.2024</p> <p>We have not yet been able to coordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network. We write to assure you that we have not forgotten about the issue and will endeavour to schedule the necessary works as soon as is practicably possible.</p>
<p>Faded yellow rumble strips on approach to bridge on A522 Beamhurst ST14 5EA Nearest postcode Meachen and Bevan</p>	<p>22.04.2024</p>	<p>4385247</p>	<p>12.07.2027</p>	<p>A highways officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.</p>

Spond Farm, Greatgate, Alton Lane, ST10 4BN Pot holes on corner.	22.04.2024	4385249	08.07.2024	At the March 2024 PC meeting it was reported that on Alton Lane, by Spond Bank Farm potholes, verge collapsed and manhole cover collapsed SCC responded on 8 th July 2024. We have not yet been able to coordinate resources to resolve the enquiry you raised, due to high demand for reactive maintenance work across our road network. We write to assure you that we have not forgotten about the issue and will endeavour to schedule the necessary works as soon as is practicably possible.
Spond Farm, Greatgate, Alton Lane, ST10 4BN manhole collapsed	22.04.2024	4385252	22.04.2024	We have visited the location provided with your report but have been unable to identify any defects that require remedial works at this time.
Spond Farm, Alton Lane, Greatgate, ST10 4BN Verges and pull ins have deep holes, side of road collapsing	22.04.2024	4385256	21.06.2024	The inspector for your area has read your report and will consider these on the next planned inspection of the area. It's important to note that all roads in our region undergo regular safety checks, either monthly, quarterly, or annually, depending on their classification. We'll continue to monitor any unresolved issues carefully – raising works once the thresholds are met.
Greatgate – very large pot hole by Pumping Station. It is filled with water, so not visible at night ST10 4HF	19.08.2024	4402838		Included photo with report
Near Abbey View Barn, on hill towards Croxden, large pothole Nearest postcode ST14 5JF	19.08.2024	4402840 4403531		Reported again, but this time with photo on 23.08.2024
Opposite Truckle House, Croxden ST14 5JD Potholes created due to water on road from flooding	19.08.2024	4402841		
JCB Golf Club, Hollington Road, ST14 5HY	23.08.2024	4403521	09.09.2024	Photo attached to report 09.09.2024 – SCC updated:

New speed limit sign knocked over				A highways officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.
Woodhouse Fields Farm, Hollington Road (by stone bridge) ST14 5HY deep pot holes x 3, just by bridge	23.08.2024	4403525	09.09.2024	Photo attached 09.09.2024 SCC updated: A highways officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problems on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time that resources become available.
Croxden Village sign Keelings Lane ST14 5JF Corner of sign damaged	23.08.2024			Not reported to SCC as damage to sign small. Clerk has a photo
Truckle House Keelings Lane ST14 5JD Deep pot hole	23.08.2024	4403529		Photo attached