Reported to Staffordshire County Council via Highways Report IT tool.

## www.staffordshire.gov.uk/reportit

Reported issue –	Date	Highways	Follow up	Comments	
location and	reported	reference	date		
requested action	•	number			
Speeding Traffic	03.06.2021	4243806		Resident sent email to Council	
along A522 –from					
Watery Lane to				Report wording was	
Madeley Farm,				Traffic calming measures have been requested by	
ST14 5EA				residents to the Parish Council to be installed along	
postcode used				the A522 from Madeley Farm to Watery Lane,	
				Beamhurst – currently cars and motor bikes	
Reported via traffic				exceed the speed limit along this stretch of the	
management, then				road, and there are a number of driveways (18) that lead onto the road and residents are	
traffic calming buttons				concerned.	
Duttoris				concerned.	
				Speeding Concerns article put on website and FB page.	
				All details given to the resident that requested	
				traffic calming measures. Clerk advised the	
				resident to ask all local residents to report their concerns to both SCC and Staffordshire Safer	
			21.07.21	Roads Partnership.	
			21.07.21	Report from Highways: This is an update to your	
				enquiry dated 03.06.2021 in relation to Uttoxeter	
				Road.	
				A highways officer has now considered your enquiry and added the following notes to your	
				report:	
				Thank you for your enquiry and apologies for the	
				delay in responding. Uttoxeter Road in Beamhurst	
				is currently under investigation and Cllr Atkins has	
				agreed to fund a feasibility study to determine the	
				issues and any suitable traffic calming solutions.	
			22.04.2024	The Parish Council are in discussions with SCC to	
				resolve the issue.	
ST14 5JD	07.12.2021	4263354		Water is collecting and not running down the grid.	
Truckle House,	01.12.2021	1200007		Parish Council Lengthsman advised it needs to be	
Croxden				jetted out.	
Grid Blocked and				Report made to Highways, stating that several	
water collects,				times in the course of the year flooding has	
covering half of		4050500		occurred (on a few occasions culminating in a large	
the road surface		4350593		pool developing on the road) making it impossible	
On the road			13.12.2021	for walkers to pass, and presenting a risk to cyclists and motorists.	
between the			13.12.2021	- บังบางเจ สาเน ทาบเบทจเจ.	
bridge spanning				Reply received stating, "A Highways inspector has	
Croxden brook				now assessed the site you reported and identified	
and the bend	10.11.2023			,,	
and the bend	10.11.2023				

where Triedle	Ţ	4054004	Т	drainaga maintananaa warka that will ha addus sasal
where Truckle House and the		4351901		drainage maintenance works that will be addressed during the next planned cleansing operation".
newly converted			20.11.2023	and the state of t
newly converted barn are situated.		4362664	20.11.2023 15.01.2024 06.02.2024	Report to Highways, "The grid line on the roadside drain is fused shut and can not be released to clear the soil and leaves from the drain. Currently there is a large amount of water collecting as the grid can not be opened to be cleared.  A further report made to Highways, "The water continues to collect after every rainfall and covers one side of the road. Please replace the grid and clean it out so that the water can run away and not cause standing water.  Reported again, as nothing done and standing water is now covering half of the road.  A Highways Officer has attended the location that you reported and completed a risk assessment. A works order has been raised and you should have now received an email explaining the priority of the works.  email received:  A highways officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not
				pose an immediate risk to public safety.
Ford Sign  Sandy Lane Greatgate ST10 4HE	07.03.2023	4314161	05.04.2023 22.04.2024	A Ford sign requested on the approach to Greatgate ford from the direction of Tean/Cheadle.  Report from Highways – Unable to Action – "Our Community Highways Team meet biannually with Councillors with a view to prioritising local issues for further investigation and/or action. Your concerns will be discussed with your local Councillor at the next Divisional Highway Programme (DHP) meeting. We receive a vast number of requests from communities for improvements to the local highway network and the DHP provides the Council with a platform to investigate some of these concerns, which may not otherwise meet the criteria for intervention". Sent email to Cllr Atkins at SCC asking for an update.
ST14 5HY Bridge crossing Nabb Brook,	26.10.2023	4348300		Report to Highways, "Damage caused to bridge when lorry reversed into it. Damage caused to first three stones on left side of
Hollington Road			26.10.23	bridge as bridge is approached from Rocester direction.
-		<u> </u>		

	1		1	D			
				Report from Highways, "Your enquiry has			
				been passed to a structural engineer to review".			
		22.04.2024 Still on system for engineer to visit					
ST10 4HE	06.11.2023	4349766	22.04.2024	Report to Highways regarding pothole on			
Between water	00.11.2020	4040700		Sandy Lane			
plant and Quarry Bank junction on Sandy Lane,			13.11.2023	Report from Highways: WORK RAISED			
Great Gate			22.04.2024	"A Highways Officer has assessed the site you reported and arranged a non-urgent work instruction. The outcome of the assessment means this defect does not pose an immediate risk to public safety. Our priority is to be effective at responding to the most serious problem on the network, therefore we are unable to provide a delivery date for defects of a non-urgent nature, until such time as resources become available". Work has been generated to resolve your request			
Greatgate – Gully blocked under tree, by Greatgate Village Green ST10 4HF	15.01.2024	4362662	22.04.2024	First noticed in November, the gully is under a tree and the tree needs removing to ensure gully is kept clear. Council obtained a quote from Lengthsman but work too big for Council to undertake. voted to report to SCC in January 2024 meeting. Your enquiry is currently allocated to a Highways officer and will be updated as soon as possible			
Faded yellow rumble strips on approach to bridge on A522 Beamhurst ST14 5EA Nearest postcode Meachen and Bevan	22.04.2024	4385247					
Spond Farm, Greatgate, Alton Lane, ST10 4BN Pot holes on corner.	22.04.2024	4385249		March 2024 PC meeting it was reported that on Alton Lane, by Spond Bank Farm potholes, verge collapsed and manhole cover collapsed			
Spond Farm, Greatgate, Alton Lane, ST10 4BN manhole collapsed	22.04.2024	4385252					
Spond Farm, Alton Lane, Greatgate, ST10 4BN	22.04.2024	4385256					

Verges and pull ins have deep holes, side of					
road collapsing Greatgate Ford	22.04.2024	4385257			
ST10 4HF	22.04.2024	4303237			
Pot holes					
Hollington Lane/Keelings Lane, Croxden nearest postcode ST14 5JD	22.04.2024	4385278			
deep silt and gravel gather on the corner of Hollington Road and Keelings					
Lane Homestead Farm	22.04.2024	4385280			
Hollington Road Croxden ST14 5JD	22.04.2024	4303200			
Running Water from broken water value in roadside verge					
I		1	1		

Last updated - 22.04.2024